
The Net Growth Rate of Polycrytalline U Wires Depends on the Fraction of (010) Pole Planes Parallel to the Wire Axis
After Buckley-1962
Net Growth Rate-G
1000
900
800
700
600
500
400
300
200
100
0
0.3
0.4
0.5
0.6
0.7
0.8
0.9
1
Fraction of (010) Plane Poles Parallel to Wire Axis