

The Growth Constant of U is Greatly Reduced at Higher temperatures
After Buckely-1964
100000
10000
1000
100
10
Net Growth Rate-G (% Growth/% BU)
0
100
200
300
400
500
600
700
800
Irradiation Temperature-°K